Approved For Release 2000/08/28-101A-RDP62S00231A000100030032-6

Chief. Requirements Breach, St/I, ORR l 25X1A9a

12 September 1958

THRU : Chief, Industrial Division, ORR Acting Chief, Aircraft Branch, D/I

Requirements for

25X1A5a1

25X1B4d

- Count and type or description of sircraft seen on Soviet airfields, particularly those adjacent to aircraft production facilities.
- 3. Description of any mirrane or mirrant engine production facilities visited by party with special emphasis on the following:
 - a. Approximate size and location of final assembly area; number of assembly lines and number of final assembly
 - b. Location, name, number and approximate size of plant Size of labor force, number of shifts worked per day, and number of days worked per week.
 - e. Current type of production and approximate monthly production rate. Approximate date when this production
 - d. Any indications of a planned production changeover. Type of new production and approximate date when first series produced model will be complete.
 - e. Previous production activity at the plant including, if possible, type, peak monthly rate, quantative production and date production ceased.
 - f. Try to find out how the Seviets schedule production. Do they make use of the learning curve (sometimes called experience curve and improvement curves)?

STOIL

Approved For Release 2000/08/23 SEIGHED P62S00231A000100030032-6

SUBJECT: Requirements for Wayne Perrish and Wife

4. Cost of the new transport aircraft broken down into as much detail as possible such as cost of airframe, cost of engines, cost of propellers, cost of equipment, etc. How many aircraft have to be sold at this price for the plant to break even?

25X1A9a

Distribution:

Orig. and 1 - Addressee

1 - D/I

2 - I/AR

ORR:D/I/AR 17/11 (3835)

25X1A9a